




Tapes-strain gauge application and inter-gauge wiring.

	<p>Pt no: HT1-xx-cl</p> <p>xx= 12mm, 25mm or 50mm</p>	<p>HT1 Polyester silicone tape.</p> <p>Carrier tape for strain gauge installation. (Max temperature 175°C) clear tape ideal for strain gauge alignment.</p> <p>Available in 12mm, 25mm or 50mm</p>
	<p>Pt no: PT1-xx-bn</p> <p>xx = 6mm, 12mm or 25mm</p>	<p>PT1 Polyimide, silicone tape. Brown.</p> <p>Carrier tape for Gauge factors HT Encapsulated strain gauges on hot substrates. Strain gauge masking for high temperature soldering (max temperature 280°C)</p> <p>Available in 6mm, 12mm or 25mm</p>
	<p>Pt no: MT1-xx</p> <p>xx = 12mm, 25mm or 50mm</p>	<p>MT1 Masking tape.</p> <p>General purpose, “crepe” style tape for masking solder dots. Temporary fixing of wiring runs. Easily removed.</p> <p>Available in 12mm 25mm 50mm</p> <p>Related product: Scalpel handle, scalpel blades, wiring tweezers and a range of hand tools.</p>